


Digital Thermometer User Manual





Main Features:

1. Indoor temperature and humidity
2. Indoor temperature with C/F selectable
3. comfortable indicator
4. Max/Min indoor temperature and humidity record
5. Magnetic back

Keys Function:

1. Press the "C/F" button to select Celsius or Fahrenheit readout
2. Press MAX button to show the record of temperature and humidity max value
3. Press MIN button to show the record of temperature and humidity min value

LCD Display



Indoor Temperature Function

- a. Temperature range: 0°C/32°F -- 50°C/122°F
- b. Accuracy: ± 1°C (0°C to 50°C)
- c. Resolution = 0.1°C
- d. The screen will show LL.L when the temperature is below 0°C, the screen will show HH.H when the temperature is above 50°C.

Indoor Humidity Function

- a. Humidity range: 20% ~ 95%
- b. Accuracy: +/- 5% RH (@250C, 30%RH to 80%RH);
- c. Accuracy: +/- 8% RH (@250C, 20%RH to 30%RH; 80%RH to 95%RH)
- d. Resolution=1%RH
- e. The screen will show 20% when the humidity is below 20%, The screen will show 95% when the humidity is above 95%.

Comfortable Indicator Function

full display	dry	less comfortable	comfortable
	Humidity is below 40%	Temperature: 20 ~ 22°C Humidity: 40%-54%	Humidity: 40%-70%

less comfortable	wet	not sure
Temperature: 20°C~22°C Humidity: 66%-74%	Humidity: above 75%	Temperature: <20°C or >28°C Humidity: 40%-74%

MAX/MIN Temperature and Humidity Memory Function

Press MAX or MIN buttons to check the temperature and humidity history record.